

FIG. 1

PU020028
 K.L. GRIMES, ET AL.
 SHEET 2 OF 9
 METHOD AND SYSTEM FOR
 MAINTAINING EVEN TUBE BURN-IN
 Vincent E. Duffy
 Telephone (317) 587-4019
 Express Mail Label EJ648049888US




FIG. 2

PU020028
K.L. GRIMES, ET AL.
SHEET 3 OF 9
METHOD AND SYSTEM FOR
MAINTAINING EVEN TUBE BURN-IN
Vincent E. Duffy
Telephone (317) 587-4019
Express Mail Label EJ648049888US




FIG. 3




FIG. 4




FIG. 5




FIG. 6

PU020028
K.L. GRIMES, ET AL.
SHEET 7 OF 9
METHOD AND SYSTEM FOR
MAINTAINING EVEN TUBE BURN-IN
Vincent E. Duffy
Telephone (317) 587-4019
Express Mail Label EJ648049888US




FIG. 7

PU020028
K.L. GRIMES, ET AL.
SHEET 8 OF 9
METHOD AND SYSTEM FOR
MAINTAINING EVEN TUBE BURN-IN
Vincent E. Duffy
Telephone (317) 587-4019
Express Mail Label EJ648049888US




FIG. 8

PU020028
K.L. GRIMES, ET AL.
SHEET 9 OF 9
METHOD AND SYSTEM FOR
MAINTAINING EVEN TUBE BURN-IN
Vincent E. Duffy
Telephone (317) 587-4019
Express Mail Label EJ648049888US




FIG. 9